

Direct Output cable installation (952-0694)




Remove (6) #4-40 lid screws.




Fold ribbon as shown



Locate HDR3 Direct Output Connector



Plug ribbon into HDR3



Place ribbon as shown



Remove blanking plate and thread standoffs through chassis into ribbon.